Tuesday, 8/21/2007 3:42:43 PM Kim Johnston **Process Sheet** : 206 L WEB **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 34169 **Estimate Number** : 10722 MA Part Number P.O. Number D2654 REV E1 This Issue 🗽 : 8/21/2007 S.O. No. **Drawing Number** Project Number N/A Prsht Rev. : LANDING GEAR **Drawing Revision** First Issue : 34075 Material Previous Run Each **Due Date** Written By Checked & Approved By 99.02.04 Fixed typo, Changed procedure DM Est Rev:D Comment Est Rev:e 06.04.05 Added level21 **Additional Product** Job Number: Description: D26007140 EXT. "I BEAM" THICK 6.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Description Part Number Batch D2600-7- 140 Web Comment: LANDING GEAR RESOURCE 1 1-Cut D2600-7 to length as per Dwg D2654 **Q** 7-8-29 2-Drill pilot holes in web using drill jig DT 8018-7 as perDwg D2654 3-Using the uni-bit, open holes to finish size as per Dwg D2654 4-Deburr holes and ends QC5 INSPECT WORK TO CURRENT STEP . 3.0 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 4.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES								
DATE	STEP	.4.	PROCEDU	RE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·					
			•							

Part No:	PAR #:	Fault Category:	NCR: Ye	s No DQA:	Date: _	<u> </u>
•			QA:	N/C Closed:	Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Corrective Action Section		Section B	Section B		Approval	Approval
DATE	STEP	Section A	Initial Action Descriptio Chief Eng Chief Eng		ption	Sign & Date	Verification Section C	Chief Eng	QC Inspector
al da	Ħ	one used has the holes		open hole to 0.  debur  Touch up with A	laline	16 784	Ør .		
07/oel30		12.C. new amployer working	BSIM5	Positive recall, Aun.	in DS.	PAURICH	03/08/31	MUL	1A0430
		on webs,							
							·		
					į				
	1								

NOTE: Date & initial all entries

Date:

Tuesday, 8/21/2007 3:42:43 PM

User:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 206 L WEB

Job Number: 34169

Part Number: D26547

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION



6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

7.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



EFFECTIVE 0708.30

<b>Dart Aerospace</b>
-----------------------

W/O:		WORK ORDER CI	CHANGES
DATE	STEP	PROCEDURE CHANGE	By Date Qty Approval Chief Eng / Prod Mgr QC Inspector
÷			
		√	
Part No	,•	PAR #· Fault Category:	NCP: Vos No DOA: Doto:

The second

QA: N/C Closed: \_\_\_\_ Date: \_

NCR:		W	ORK OR	DER NON-CONF	ORMANCE (NCR)				
	T	Description of NC	Corrective Action Initial Action Descri Chief Eng Chief Eng		iption Sign &		Varification	A	
DATE	STEP	Section A					Verification Section C Approval Chief Eng		Approval QC Inspector
							:		-
-									
						ļ	1.7		

NOTE: Date & initial all entries





D

E

EI

98.01.15

04.05.26


04.08.04


)	DESIGN DRA		DRAWN BY	DART AEROSPACE USA, INC.					
′	CHECH	KED W	APPROVED NI	DRAWING NO. RE	V. E				
		#	#	D2654 SHEET 1 C	)F 2				
	DATE		A	TITLE	CALE				
	04.0	5.26		WEB	1:20				
	Α		97.03.25	NEW ISSUE					
	В		97.06.26	ALTER HOLE PATRN., 0.500 WAS 0.43	8				
	С		97.10.29	CHANGED HOLE PATTERN					


GHW HOLES CHANGED TO Ø0.63


CHANGE LENGTHS, REFORMAT

PER TOOLING, BO.B WAS BO.S










MAKE FROM D2600—5—108 EXTRUSION FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED


SUBJECT TO AMENDMENT WITHOUT NOTICE








DESIGN ()	DRAWN BY	DART	AEROSPACE PORT HADLOCK,	
CHECKED	APPROVED	DRAWING NO. D2654	**	REV. E SHEET 2 OF 2
DATE		TITLE		SCALE
04.05.26	•	WEB		1:20



Copyright © 1997 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.



## Jason Murdoch

From: David Shepherd [dshepherd@dartaero.com]

Sent: Friday, August 31, 2007 11:17 AM

To: 'Jason Murdoch'

Subject: RE: NCR D2554-7 B34169

Either option is acceptable to me, as long as we have decent edge distance to the front of the web. The decision is yours.

David

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: Thursday, August 30, 2007 1:42 PM

To: 'David Shepherd'

Cc: 'L Lacelle'

**Subject:** NCR D2554-7 B34169

Hi Dave. There was 1 web that the most fwd hole was ovalized upon drilling. The hole is supposed to be 0.500", and the widest part of the hole is close to 0.600". I debured it as round as I could get it, leaving it 0.550" — 0.610". Can we leave this as is, or can we open it to 0.625" to make it round?

jmurdoch@dartaero.com Q.C. COORDINATOR

No virus found in this incoming message.

Checked by AVG Free Edition.

Version: 7.5.484 / Virus Database: 269.12.12/979 - Release Date: 8/29/2007 8:21 PM

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.484 / Virus Database: 269.12.12/979 - Release Date: 8/29/2007 8:21 PM